

AvaLung Pack Recall

Reinach, Switzerland (December 10, 2010) - Black Diamond Equipment AG has reported and is working with the E.C. Consumer Product Safety Commission on a voluntarily-announced recall of a limited portion of 2010 Black Diamond AvaLung Packs because of a possibility that the intake tubing may crack under cold temperatures.

The recall only pertains to a limited manufacturing run of Black Diamond AvaLung Packs produced in 2010, which can be identified by the following PO# and model combination:

PACK STYLE	COLOR	SIZE	PO #	PACK STYLE	COLOR	SIZE	PO #
	BLACK	M/L	101153, 101254		BLACK	M/L	101104, 101254, 101330, 101287
		S/M	101104			S/M	101030
					GREEN OLIVE PRINT	M/L	101104, 101030, 101052
	BLACK	-	101052, 100981			S/M	101104
	GREEN OLIVE	-	100957		OCEAN PRINT	M/L	101104, 101052, 101030
	SETH PLAID	-	101030			S/M	101104
	RED SETH		101254		BLACK	M/L	101254, 101104, 101287
	PLAID ORANGE				CHILI	M/L	101213, 101254, 101030, 101052
	BLACK	M/L	101104, 101271, 101254			S/M	101104
		S/M	101052, 101104, 101322	BANDIT	BLACK		
	GREEN OLIVE	M/L	100981, 101052			•	101322, 101330, 101052
	BLACK	M/L	101330	NOTE: If the exact combination of			
		S/M	101104	your AvaLung pack's model name and PO# is not listed in the above list, it is not affected by this recall.	P		NW 61505 A10241 Storesten Stressen Stre
	OCEAN PRINT	M/L	101104, 101153	Beneficial and a second and a			ANDEL AND THE AND
		S/M	101104		PO#		

Any AvaLung Pack that falls within the criteria above should be immediately returned to Black Diamond for replacement (anticipated replacement time is March 2011).

2010 AVALUNG PACK RECALL

For help identifying the affected packs, for return instructions and/or questions on the status of your replacement, please contact Black Diamond at <u>recall@blackdiamond.eu</u>. In case you want to speak to one of our Representatives, please let us know your phone number to have us call you back.